

GREG BELL
Lieutenant Governor

# State of Utah

**DEPARTMENT OF NATURAL RESOURCES** 

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:				
OGM	Pete Hess Environmental Scientist III			

(4

# **Inspection Report**

Permit Number:	C0070045
Inspection Type:	COMPLETE
Inspection Date:	Monday, April 12, 2010
Start Date/Time:	4/12/2010 1:13:00 PM
End Date/Time:	4/14/2010 2:20:00 PM
Last Inspection:	Tuesday, March 09, 2010

Inspector: Pete Hess, Environmental Scientist III
Weather: Overcast; very windy. 24 to 40 MPH gusts.

InspectionID Report Number: 2323

**Types of Operations** 

Accepted by: jhelfric 5/6/2010

Permitee: **HEADWATERS ENERGY SERVICES**Operator: **HEADWATERS ENERGY SERVICES** 

Site: COVOL SITE

Address: 1865 S RIDGE RD, WELLINGTON UT

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: PROPOSED

^	4	A		
Curi	ent	ACI	eag	es

Total Permitted	30.00
Total Disturbed	30.00
Phase I	
Phase II	
Phase III	

# Mineral Ownership

# Federal Underground State Surface County Loadout Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Wind velocities (southerly) in the County were ranging from 24 to 40 MPH on April 12, 2010. This data was confirmed by the Permittees weather station located in the office trailer.

Mr. Kyle Edwards, Plant Manager, represented the Permittee on April 14, 2010.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Date

Thursday, April 15 2010



Permit Number: C0070045 Inspection Type: COMPLETE

Inspection Date: Monday, April 12, 2010

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>V</b>			
3.	Topsoil	<b>✓</b>			
4.a	Hydrologic Balance: Diversions	<b>~</b>			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	<b>~</b>			
4.d	Hydrologic Balance: Water Monitoring		<b>✓</b>		
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		<b>~</b>		
6.	Disposal of Excess Spoil, Fills, Benches		<b>✓</b>		
7.	Coal Mine Waste, Refuse Piles, Impoundments		<b>✓</b>		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	<b>V</b>		<b>~</b>	
10.	Slides and Other Damage		<u> </u>		
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading		<b>✓</b>		
13.	Revegetation	<b>✓</b>		<b>✓</b>	
14.	Subsidence Control		✓		
15.	Cessation of Operations		<b>✓</b>		
16.a	a Roads: Construction, Maintenance, Surfacing	<b>✓</b>			
16.Ł	Roads: Drainage Controls	<b>V</b>		<b>V</b>	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit	<b>V</b>			
21.	Bonding and Insurance	<b>✓</b>		<b>✓</b>	
22.	Other	<b>V</b>		<b>V</b>	

Permit Number: C0070045 Inspection Type: COMPLETE

Inspection Date: Monday, April 12, 2010

Page 3 of 3

### 4.b Hydrologic Balance: Sediment Ponds and Impoundments

The east and west ponds were inspected. The west pond contains some water, but both are well below the discharge elevation. The pond inlet ditches were stable.

# 9. Protection of Fish, Wildlife and Related Environmental Issues

Ms. Gina Rau, Environmental Manager for the Permittee, has discussed the needs of the 2010 spring nesting season burrowing owl survey with Mr. Joe Helfrich, Division Biologist, and Dr. Patrick Collins of Mt. Nebo Scientific. It appears that the field survey for this Permit requirement will be addressed sometime in June, 2010.

## 13. Revegetation

Topsoil piles at the site are to be seeded this spring.

### 16.a Roads: Construction, Maintenance, Surfacing

Scamp Excavation was grading the roads at the site this day.

## 16.b Roads: Drainage Controls

Many of the sites diversions were redefined by Scamp Excavation this day. Mr. Edwards intends to slope the east side perimeter road to the inside for better drainage control.

# 21. Bonding and Insurance

The current general liability insurance remains in effect through October 1, 2010. Coverage amounts are adequate. The cancellation clause meets the requirements of the R645 Coal Mining Rules.

#### 22. Other

Headwaters, Inc. submitted the 2009 Annual report for the COVOL site on February 19, 2010. The Division completed the review of that submitted information on February 25, 2010.